

Damage caused by Typhoon Mangkhut on 16/9/2018 (Sunday)

Tennis Courts

Part of the Tennis Courts' fence was blown down. It leaned on the pavement of Wylie Road while other sides of the fence were bent and twisted. Because the side facing Wylie Road is removed, the tennis courts are not suitable for use and are currently closed. It will be fixed by the EDB but we will need professional advice from the P.E. department, tennis coach and past students. Currently the tennis team is hiring tennis courts outside for practice.



16th September 2018



18th September 2018



Swimming Pool

The fence of the swimming pool facing the Emergency Vehicle Exit is slanted. It does not cause immediate danger as long as students do not get close to it. The EDB will fix it and require opinions from the P.E. Department and past students.

Tall branches of a big tree at the swimming pool area were broken and require machines to trim. There were lots of leaves and small branches in the pool. Luckily some janitors, students and teachers helped to clean it immediately so that students could use the pool for practise the next day.

Sports Facilities

A lot of sports and fitness equipment was blown to the side of the swimming pool and was damaged. Equipment includes Climbers, Flex strider, mats, hurdles, football goals and nets. This requires donations. Estimated cost: HK\$150,000



Classrooms

The glass walls of 4 classrooms (used to be the French windows) were broken (Rm 115, 116, 215 & 216). The air conditioners, lights, computers and projectors were damaged. The 4 classes have to be relocated to other rooms for lessons for about 8 weeks. The EDB will cover all the expenses of the repairs.



16th September 2018



19th September 2018



Spalling

Cement dropped from the roof of the corridor from the VP office to the chapel. The EDB will repair it.

Chapel Fence

The fence outside the main entrance of the chapel was broken. The EDB will repair it.



White Jade Orchid Tree

The White Jade Orchid tree near the west gate planted at the 75th anniversary (1999) was toppled by the typhoon. It blocked the pathway from the west gate to the school. Part of it was removed so that students could enter the school through the west gate the next day. However, most part of it was left untreated on the ground. It is difficult to re-plant it again as most of the roots were torn apart. Before it is removed, we hope some of the wood could be kept to make souvenirs. This would require specific wood-crafting agencies to help.



Damage to trees

Damage to trees was severe. Many trees were uprooted or snapped off and many more had all leaves and small branches stripped off so that only bare trunks remained around the campus. We need funding to remove the branches and tress. We are also looking for arborists or landscape architects among past students and BAGUIO Cleaning Services Company Limited (碧瑤清潔服務有限公司), to assess the conditions and decide how to re-plant trees on campus. Estimated cost: \$500,000. (Government funding: \$150,000)



Other damage includes... Estimated cost: \$100,000



Arbor Amoris



Stevenson Screen



Bulletin Boards



Wall lights



Water leakage at control room

Rough Estimation:

Sports equipment	\$150 000
Trees	\$350 000
Other facilities	\$100 000
<hr/>	
Total	\$600 000